

































Assembly Instructions

1 Hardware List


	A	M6x35mm	8pcs		B	Ø15x10mm	8pcs		C	Ø6x30mm	8pcs
	D	M3.5x12mm	24pcs		E	M4x35mm	6pcs		F	M6x28mm	8pcs
	G	M6x40mm	4pcs		H		2pcs		I		4pcs
	J	M4x12mm	6pcs		K	Ø2x16mm	20pcs		L		4pcs
	M	Ø6x30mm	2pcs		N		2pcs		O	40*15	2pcs
	P	M4mm	1pc		Q		8pcs				



2 Parts List


							
①	1pc	②	1pc	③	1pc	④	1pc
							
⑤	1pc	⑥	1pc	⑦	2pcs	⑧	1pc
							
⑨	2pcs	⑩	2pcs				








3




STEP 1 A -  x 4 B -  x 4




STEP 2

A -  x 4 B -  x 4 C -  x 4 J -  x 2 N -  x 2




STEP 3


C -  x 4 E -  x 4




STEP 4 **G -  x 4** **P -  x 1**




STEP 5 **F -  x 8** **P -  x 1**



STEP 6 I -  x 4 Q -  x 8





STEP 7 K -  x 20





STEP 8

E -  x 2 M -  x 2



STEP 9

D -  x 24 H -  x 2 J -  x 4 L -  x 4 O -  x 2



STEP 10

